

UPÍNÁNÍ PRO STAR

Stroj	Vodící pouzdro	Kleština do vřetene	Kleština do protivřetene
SA12/16	J7AR	F20/87	F20/87
SA26RC	J7AR	F20/87	F20/87
SB16	J7AR	F20/87	F20/87
SE16	J7AR	F20/87	F20/87
SI12NP	J7AR	F20/87	F15/580
SH7	J6	F15/580	F15/580
SH12	B301	F20/87	
SH16	J7AR	F20/87	F20/87
SR10J	J6	F15/580	
SR16	J7AR	F20/87	F20/87
SR16R	J7AR	F20/87	F20/87
SR20	B261	F25/64	F25/64
SR20R	B261	F25/64	F25/64
SR20R II	B261	F25/64	F25/64
SR32	J9	F37/740	F37/740
SV12	J7AR	F20/87	F20/87
SV20	B261	F25/64	F25/64
SV32	J9	F37/740	F37/740
SV32J	J9	F37/740	F37/740
SV32J II	J9	F37/740	F37/740
SW7	J4ST	F15/580	F15/580
SW7R	J6	F15/580	F15/580

technická podpora ☎ +420 774 454 024

